SEGNET

Approved For Release 2004/07/08: CIA-RDP81B00879R001000100123-8

OXC - 4382 Copy <u>3</u>01 4

25X1

25X1 25X1 25X1

22 January 1963

	MEMORANDUM FOR THE RECORD							
5X1	SUBJECT : Briefing By On Status Of Aero Medical Support and Personal Equipment							
	1. The following people were in attendance:							
25X1	Mr. Cunningham Mr. Parangosky							
5X1	reviewed the evacuation plan which will be put into effect in case of serious injury to contractor or Air Force personnel. The over-all medical treatment available was							
25X1	of							
	3. Problems in the personal equipment area which are being worked in include the following:							
	A. Cxygen Consumption							
	Studies have been undertaken at the Firewel Company to determine oxygen consumption as a result of exercise in an							

B. Suit Mounted Altimeter

necessary to solve this problem.

A decision to authorize this item is being held up pending further investigation.

seated valves. A double face seal may ultimately be

effort to account for the increased consumption rates being experienced by the pilots while flying vs. their altitude chamber runs. One possible explanation might be in the fact that we have switched from soft seated valves to hard

DOCUMENT NO. ///, C.	Heated Visor vs. Reflection
MO CHANGE IN SLASS. A TO PROCLASSIMED CLASS, CHANGED TO: TS S C MENT REVIEW DATE:	THE WAY WIND MARKETON AND AND AND AND AND AND AND AND AND AN
NEXT REVIEW DATE: AUTH: HR 70-2 Approve DATE://// REVIEWER:	1011/ For Release 2004/07/08 : GIA-RDP81B00879R001000100123-8

25X1

OXC-4382 Page 2

visor clear at extremely cold temperatures. Our present gold coating of the visor only gives .07 watt per square centimeter. If additional gold coating is applied the reflection problem is greatly increased. The David Clark Company is investigating several different approaches to this problem.

D. Personal Equipment Van

If another van is ordered the possibility of ordering two small vans that could be attached should be investigated. This would enhance expeditious moving of the vans. The present van requires a C-130 aircraft for airlift.

E. Ejection Seat System

	It is	under	stood	that	if t	he pr	imary	eject	ion se	sat aye	tem
fai	is to i	function	on pro	perly	the	pilo	t has	no al	ternat	te syste	m
of (eqaose	other	then	OVET	the	aide	after	manua	lly re	moving	
	canopy						low up			100	

|s/

25X1

Distribution: 1-DD/OSA 2-C/DD/OSA 3-RB/OSA 4-DD (Chrono) DD/OSA

25X1

25X1